



# Work Order

## WORK ORDER INFORMATION

**Work Order Name:** WO/70007HR4346/1

**Work Order Type:** Weatherization

**Audit Name:** Audit (86)

## CLIENT INFORMATION

**Client Name:**

**Address:**

**Client ID:** 70007HR4346

**Alt. Client ID:**

## AGENCY INFORMATION

**Agency:** HREC

**Agency Phone:** (931) 289-4101

**Address:** P.O Box 208  
Erin, TN 37061

**Fax:**

**Email Address:** lewis@hrec.org

**Agency Contact:** Adamson, James R

**Work Phone:** (615) 478-1355

**Cell Phone:** (615) 478-1355

**Email Address:** jamieadamson@rocketmail.com

**Company Name & License Number:** \_\_\_\_\_

**Contractor's Signature:** \_\_\_\_\_

## COMMENT

Work Order By: James Adamson

Blower Door 50 Pascals @ 5452 CFM's

House Age 1950 / 1144 SF

---

**Client Name:**

**Client ID:** 70007HR4346

**Alt. Client ID:**

### **Work Order**

Work Order Name: WO/70007HR4346/1

Report Run On: 5/13/2010

DOE Weatherization Assistant

Version 8.5.0

Page 1 of 6

## Measures

Measure 1 Infiltration Redctn		Components				Inspected			
<b>Comment</b> Air Infiltration.						<input type="checkbox"/>			
<p>1. Install weatherstrip and doorsweep in both front right and left bedroom closets.</p> <p>2. Seal holes in floor next to water heater, small holes can be caulked.</p> <p>3. Caulk crown in following rooms with clear paintable caulk:</p> <p>A. Bed 17' 8" x 13' 4"</p> <p>B. L/R 80' around perimeter.</p> <p>C. Kitc 10' x 11'</p> <p>D. Bath 36' around perimeter.</p> <p>E. Caulk around fiberglass shower.</p> <p>4. Install new steel pre-hung door unit at front entrance in place of hollow core door. Include interior trim, kwickset door lock, and caulk interior and exterior.</p>									
#	Material / Labor	Description /Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
10	Miscellaneous Supplies	Infiltration Reduction	Each	4			<input type="text"/>	<input type="text"/>	<input type="text"/>
<b>Other Detail</b>									
							<input type="text"/>	<input type="text"/>	<input type="text"/>
							<input type="text"/>	<input type="text"/>	<input type="text"/>
<b>Measure Sub Total:</b>							<b>Sub Total:</b> <input type="text"/>		
<b>Field Notes:</b>									

**Measure 2 DWH Pipe Insulation****Components****Inspected****Comment** First Five Feet Mandatory.☐

				Estimated			Actual		
#	Material / Labor	Description /Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	DHW Pipe Insulation	Each	1			<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	DHW Pipe Insulation	Each	1			<input type="text"/>	<input type="text"/>	<input type="text"/>
Other Detail									
<input type="text"/>		<input type="text"/>					<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>		<input type="text"/>					<input type="text"/>	<input type="text"/>	<input type="text"/>
Measure Sub Total:							Sub Total: <input type="text"/>		

**Field Notes:****Measure 3 DWH Tank Insulation****Components****Inspected****Comment**☐

		Estimated				Actual			
#	Material / Labor	Description /Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Hot Water Equipment	DHW Tank Insulation	Each	1			<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	DHW Tank Insulation	Each	1			<input type="text"/>	<input type="text"/>	<input type="text"/>
Other Detail									
<input type="text"/>		<input type="text"/>					<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>		<input type="text"/>					<input type="text"/>	<input type="text"/>	<input type="text"/>
Measure Sub Total:							Sub Total: <input type="text"/>		

**Field Notes:**

Client Name:  
Client ID: 70007HR4346  
Alt. Client ID:

**Work Order**  
Work Order Name: WO/70007HR4346/1  
Report Run On: 5/13/2010

DOE Weatherization Assistant  
Version 8.5.0  
Page 3 of 6

**Measure 4 Attic Ins. R-38****Components** A1**Inspected**

**Comment** Include install new attic hatch sized according to S.W.F.G. Consult homeowner on where to install.

☐

Include styrofoam baffles and pack voids between baffle and top plate with fiberglass batt.

#	Material / Labor	Description /Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	Attic Insulation - Cellulose, Blown - R-38	SqFt	1144			<input type="text"/>	<input type="text"/>	<input type="text"/>
<b>Other Detail</b>							<input type="text"/>	<input type="text"/>	<input type="text"/>
							<input type="text"/>	<input type="text"/>	<input type="text"/>
<b>Measure Sub Total:</b>							<b>Sub Total:</b>	<input type="text"/>	

**Field Notes:****Measure 5 Replace A/C****Components** AC1**Inspected**

**Comment** Include seal around A/C unit with rigid foam board and caulking.

☐

#	Material / Labor	Description /Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Cooling Equipment	Window A/C - w/heat strip	Each	1			<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	Window A/C - w/heat strip	Each	1			<input type="text"/>	<input type="text"/>	<input type="text"/>
<b>Other Detail</b>							<input type="text"/>	<input type="text"/>	<input type="text"/>
							<input type="text"/>	<input type="text"/>	<input type="text"/>
<b>Measure Sub Total:</b>							<b>Sub Total:</b>	<input type="text"/>	

**Field Notes:**

Client Name:  
Client ID: 70007HR4346  
Alt. Client ID:

**Work Order**  
Work Order Name: WO/70007HR4346/1  
Report Run On: 5/13/2010

DOE Weatherization Assistant  
Version 8.5.0  
Page 4 of 6

**Measure 6 CO Monitor is Needed****Components****Inspected****Comment**☐

#	Material / Labor	Description /Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety Items	CO monitor	Each	1			<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	Labor	Hour				<input type="text"/>	<input type="text"/>	<input type="text"/>
Other Detail									
<input type="text"/>							<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>							<input type="text"/>	<input type="text"/>	<input type="text"/>
Measure Sub Total:							Sub Total: <input type="text"/>		

**Field Notes:****Measure 7 Fix Improper Venting (Clothes Dryer)****Components****Inspected****Comment** Install metal flex pipe and vent to exterior of home. Include exterior vent trim.☐

#	Material / Labor	Description /Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety Items	Equipment	Each	1			<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	Labor	Hour	1			<input type="text"/>	<input type="text"/>	<input type="text"/>
Other Detail									
<input type="text"/>							<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>							<input type="text"/>	<input type="text"/>	<input type="text"/>
Measure Sub Total:							Sub Total: <input type="text"/>		

**Field Notes:**

Client Name:  
Client ID: 70007HR4346  
Alt. Client ID:

**Work Order**  
Work Order Name: WO/70007HR4346/1  
Report Run On: 5/13/2010

DOE Weatherization Assistant  
Version 8.5.0  
Page 5 of 6

**Measure 8 Smoke Detector is Needed****Components****Inspected****Comment**

#	Material / Labor	Description /Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety Items	Smoke detector	Each	1					
2	Labor	Labor	Hour	1					

**Other Detail**

<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>

<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>

**Measure Sub Total:****Sub Total:****Field Notes:****Work Order Grand Total:****Grand Total:**

Client Name:

Client ID: 70007HR4346

Alt. Client ID:

**Work Order**

Work Order Name: WO/70007HR4346/1

Report Run On: 5/13/2010

DOE Weatherization Assistant

Version 8.5.0

Page 6 of 6